IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System — G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Wincoff Marble & Granite DATE 2/3/78 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 64-70W

S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ( ) Mobile Home ( ) Business (X) Other _____

No. Bedrooms 2 No. Bathrooms _____

Garbage Disposal Unit	Yes ( )	No ( )	
Auto. Dishwasher	Yes ( )	No ( )	
Auto. Wash. Machine	Yes ( )	No ( )	
Site Suitable	Yes ( )	No ( )	

Lot Area _____

Character & Porosity of Soil _____


Percolation Rate _____

Topography _____

Depth to Water Table _____

Rock or other impervious formations _____

Repair



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines _____

Sq. Ft. _____ Linear Ft. _____

Depth of Stone in Lines _____

Water Supply: Individual ( )

Public ( )

Installed by Roy Lentz

IMPROVEMENTS PERMIT BY _____

COMMENTS: New tank installed - drain line appears to be good old tank filled with soil, new tank 10' from property line

CERTIFICATE OF COMPLETION BY Andrew E. Young DATE 2/3/78

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold