DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Rick Labuda
ADDRESS:
PROPOSED FACILITY: 3 BR modular
PROPOSED DESIGN FLOW (.1949): 360 gpd
LOCATION OF SITE: Monticello Dr.
APPLICATION DATE _____
DATE EVALUATED: 16 Feb 07
PROPERTY SIZE: _____
PROPERTY RECORDED: _____

WATER SUPPLY: ☐ Private ☑ Public ☐ Well ☐ Spring ☐ Other _____

EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 15%	0-11	gr / L	vfr / ss,p	7.5YR	>48"			PS 0.25
		11-40	sbk / C	fi / ss,p					
		40-48+	wsbk / C	fi / ss,p					
2	H/L 15%	0-10	gr / L	vfr / ss,p	7.5YR	36"			PS 0.25 2½" fmd.
		10-29	sbk / C	fi / ss,p					
		29-36	wsbk BC / ss,p	fr / ss,p					
		36+	SAP						
3	L 15%	0-10	gr / L	vfr / ss,p	7.5YR	7.5YR			PS 0.25
		10-41	sbk / C	fi / ss,p					
		41-48+	wsbk / C	fr / ss,p					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	II	II
Site LTAR	0.25	0.25

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: TCH
OTHER(S) PRESENT: _____

COMMENTS: 5 lots 72' in length. 360' to [illegible]