DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 28 Dove Meadows PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | | 0-10 | BSCL GR | fri SSSP | | | | | .3 to 42" |
| | | 10-42 | RCL MFSBK | fri SSSP | | | | | |
| | | 42+ | ROCK | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 2 | | 0-7 | BSCL GR | fri SSSP | | | | | PS .3 to 42" |
| | | 7-24 | RCL MFSBK | fri SSSP | | | | | |
| | | 24-42 | B/C CL FWSBK | WSBK fri SSSP | | | | | |
| | | 42+ | | | | | | | |
| | | | | | | | | | |
| 3 | | 0-10 | BSCL GR | fri SSSP | | | | | PS .3 to 48" |
| | | 10-48 | RCL MFSBK | fri SSSP | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 4 | | 0-6 | SICL GR | fri SSSP | | | | | .15 LP to 26" |
| | | 6-26 | RCL MSBK | fri SSSP | | | | | |
| | | 26-32 | WROCK r | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____