IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR GRIER PHARR DATE 10-12-88 PERMIT NO. 10D.

PHONE: Business _____ Home _____

LOCATION: Hwy 115N-T.L. on old Wilkesboro Rd.-T.L. on Bradley Farm Rd. House on Dat Moseley Dr. S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other Repair

No. Bedrooms 2 No. Bathrooms 1.5

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil Appears Suitable.
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate Good / 5g. ft.
Auto. Wash. Machine	Yes (✓)	No ( )	Topography Level
Site Suitable	Yes (✓)	No ( )	Depth to Water Table 10'+
			Rock or other impervious formations none observed.

Lot Area 1 acre.

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System

Size of Tank EXISTING Gals.

Nitrification Field:
No. of Lines 2
Sq. Ft. 600+ Linear Ft. 200+
Depth of Stone in Lines 12

Water Supply: Individual ( )
Public (✓)

Installed by Wes Lyttle

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Darrell Wagner

COMMENTS: New tank installed + tank pumped.

CERTIFICATE OF COMPLETION BY Steve Barnes DATE 10-12-88

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

Location of the proposed Front Porch addition does not appear to impact the existing on-site septic system.**NOTE: _____

_____ REHS

Date: September 24, 2013

ICHD-Environmental Health Division