IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System — G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR B. A. Daniels DATE 8/12/77 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Northmont Sub. Division off of old Wilkesboro Rd. on Morrison Drive S. R. No. _____

SUBDIVISION NAME Northmont LOT NO. 75 SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 4 No. Bathrooms 3

Garbage Disposal Unit	Yes	(✓)	No	( )
Auto. Dishwasher	Yes	(✓)	No	( )
Auto. Wash. Machine	Yes	(✓)	No	( )
Site Suitable	Yes	(✓)	No	( )

Lot Area 20,000 sq ft+

Character & Porosity of Soil Red Clay
Percolation Rate _____
Topography Slight Slope
Depth to Water Table Low
Rock or other impervious formations None



Plot of System

Size of Tank 1500 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 10"
Water Supply: Individual ( )
Public (✓)
Community
Installed by B. A. Daniels

IMPROVEMENTS PERMIT BY _____

COMMENTS: Surface water and downspouts should be diverted away from Septic Tank & lines.

CERTIFICATE OF COMPLETION BY E. A. Stevenson DATE 8/12/77

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold