DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Stanford Bldg Co. APPLICANT: Jim Nelson
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3/5/96
PROPOSED FACILITY: 3BR House w/ CL PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Bi-Rose Farm Road, off Fawnwood Rd on Rt. PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed
Fawnwood Lot #6 Top

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL. CLASS & LTAR
1	6% Linear	0-6	scl	Fr ss sp sPor					PS .25
		6-24	scl	Fr ss sp sPor					
		24-26	scl/sap	Fr ss sp sPor					
		26-28	sap (s) sl	wEp					
2	5% Linear	0-6	scl	Fr ss sp sPor					PS .25
		6-20	scl	Fr ss sp sPor					
		20-30	scl/sap	Fr ss sp sPor					
		30-48	sap (s) l	wEp					
3	5% Linear	0-8	scl	Fr ss sp sPor					PS .25
		8-24	cl	Fr ss sp sPor					
		24-27	scl	Fr ss sp sPor					
		27-31	scl/sap	Fr ss sp sPor					
		31-48	sap (s) gl	wEp					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	25% Reduction Conv.	Same as Initial Pump
Site LTAR	.25	.25

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: Bill Johnson
OTHER(S) PRESENT: _____