DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Bullock
ADDRESS: _____ APPLICATION DATE _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): 360 gpd DATE EVALUATED: _____
LOCATION OF SITE: Woodrock Rd # 18 PROPERTY SIZE: .731
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☒ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 10%0	0-7	sbk / c	fi / sap	748	30	PS		PS 0.7
		7-30	mssbk / scl sap	fr / sap					
		30+	sap						
2	L 10%	0-5	mssbk / scl	vfr / sap	748	14	PS		PS 0.7
		5-14	sbk / scl sap	fr sap					
		14+	sap						
3	L 10%	0-11	sbk / c	fi / sap	748	11	PS		PS 0.7
		11+	sap / scl	fr / sap					
4	L	0-5			748	39	PS		PS 0.7
		5-39	sbk / c	fi / sap					
		39+	sap / cl	fr /					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	II	II
Site LTAR	0.7	0.7

OTHER FACTORS (.1946): PS
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: TCH
OTHER(S) PRESENT: _____

COMMENTS: _____