IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Lawrence Barbour DATE 19 Oct 76 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Hwy 115 N. 3rd house on left after crossing South Yadkin River

S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 1

Garbage Disposal Unit	Yes ( )	No (✓)
Auto. Dishwasher	Yes ( )	No (✓)
Auto. Wash. Machine	Yes (✓)	No ( )
Site Suitable	Yes (✓)	No ( )

Character & Porosity of Soil Cecil Clay


Percolation Rate Rare

Topography 2-6% Slope

Depth to Water Table Rock

Rock or other impervious formations Rock

Lot Area Large



Plot of System

Size of Tank Existing Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 900 Linear Ft. 300

Depth of Stone in Lines 10"

Water Supply: Individual (✓)

Public ( )

Installed by Harlee Lasley

IMPROVEMENTS PERMIT BY _____

COMMENTS: Tank pumped. New Tee installed

Relocation of drain line due to extended right of way of Hwy 115 N.

CERTIFICATE OF COMPLETION BY W M Tolbert DATE 19 Oct 76

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold