DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Frank Lavery APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
PROPOSED FACILITY: 4 Bedroom PROPOSED DESIGN FLOW (.1949): 480 gpd PROPERTY SIZE: 1.0 Ac.
LOCATION OF SITE: State Park Rd Lot 1 PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☒ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	5%	0-5	Brscl wsbk	Frssssp	Common OB mottles Chroma 2 @ 35"	35"	—	—	PS 0.225
		5-40	Rc sbk	Frsssp					
		40-48	Rcl sbk	Frsssp	No mottles				
2		0-31	Rc sbk	Frsssp	—	48"	—	—	PS 0.3
		31-48	Rcl sbk	Frsssp					
3		0-36	Rc sbk	Frsssp	—	48"	—	—	PS 0.3
		36-48	Rcl sbk	Frsssp					
4		0-39	Rc sbk	Frsssp	—	48"	Few Inc sapQ 30"	—	PS 0.3
		39-48	Rcl sbk	Frsssp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Frank Lavery
ADDRESS: ___
APPLICANT: ___
APPLICATION DATE: ___
DATE EVALUATED: ___
PROPOSED FACILITY: 4 Bedroom
PROPOSED DESIGN FLOW (.1949): 480 gpd
PROPERTY SIZE: 1.00 Ac
LOCATION OF SITE: State Park Rd Lot 1
PROPERTY RECORDED: ___
WATER SUPPLY: ☒ Private ☐ Public ☒ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL CLASS & LTAR
5	5%	0-5	Br scl wsbk	Frsssp	4B mottles chroma 2 @ 37"	37"	—	—	PS 0.225
		5-41	Rc sbk	F-Frsssp					
		41-48	Rcl sbk	Frsssp					
6		0-5	fill		Common 4B mottles	48"			PS 0.225 to 19" 0.3 19"-48"
		5-19	R4 c sbk/abk	F-Frsssp					
		19-40	R c sbk	Frsssp	No 4B mottles				
		40-48	R cl sbk	Frsssp					
7		0-8	Br scl wsbk	Frsssp	4B mottles chroma 2 @ 27"	27"	—	—	PS 0.225
		8-27	Rc abk	F-Frsssp					
		27-	chroma 2						
8		0-8	Br scl wsbk	Frsssp	4B mottles to 26"	48"	—	—	PS 0.225 to 26 0.3 26"-48"
		8-40	Rc sbk/abk	F-Frsssp					
		40-48	Rcl wsbk	Frsssp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	1605 Ft²	540 Ft²
System Type(s)	25% Reduct.	PPBPS
Site LTAR	0.225	0.3

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: GM
OTHER(S) PRESENT: ___

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Frank Laverty
APPLICANT: _____
ADDRESS: _____
APPLICATION DATE: _____
DATE EVALUATED: _____
PROPOSED FACILITY: 4bedroom
PROPOSED DESIGN FLOW (.1949): 480gpd
PROPERTY SIZE: 1.00Ac
LOCATION OF SITE: State Park Rd. Lot 1
PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☒ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL CLASS & LTAR
9	5%	0-8	Brscl wsbk	Frssp	YB mottles chroma 2 @ 30"	30"	—	—	PS 0.22
		8-30	RC sbk/Abk	F-Frssp					
10		0-8	Brscl wsbk	Frssp	YB mottles chroma 2 @ 30"	30"	—	—	PS 0.225
		8-30	Rc sbk/Abk	F-Frssp					
11		0-24	Rc sbk	Frssp	chroma 2 @ 27"	27"	—	—	PS 0.225
		24-27	Rc sbk/Abk	F-Frssp					
12		0-26	Rc sbk	Frssp	—	48"	Inc sap @ 30"	-	PS 0.3
		26-48	RCl sbk	Frssp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____