ON-SITE WASTEWATER SECTION

COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____

ADDRESS: _____

PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): 360 gpd DATE EVALUATED: 9-15-03

LOCATION OF SITE: lot 2 Snake Creek PROPERTY SIZE: _____

WATER SUPPLY: ☒ Private ☐ Public ☒ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____

EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut

TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	8%	0-4	gr-wkfsbk brn sl cl	frsssp					.3
		4-7	wkfsbk rbrn sl cl	frsssp					
		7-16	wk-mfsbk R hue sl cl	fr sssp scvp					
		16-46	wkfsbk R-yR cl	fi sssp scvp					
		46-61	variable L/fs/sap	frsssp					
2		0-20	mfsbk R cl	frsssp scvp					.3
		20-62	wkfsbk-massive R-yR L/fs/sap	frsssp					
3		0-8	wkfsbk brn-rbrn sl cl	frsssp					.25-.3
		8-28	wk-mfsbk R cl	frsssp L/ls/sap					
		28-60	(B-C) wkfsbk R-yR L/ls/sap mottled	frsssp					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	Grav 25%	Grav Trench
Site LTAR	.25-.3	.25-.3

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): S

EVALUATED BY: DH

OTHER(S) PRESENT: _____

COMMENTS: _____