ON-SITE WASTEWATER SECTION

COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Russ Graham APPLICATION DATE _____

ADDRESS: _____ DATE EVALUATED: 9-15-03

PROPOSED FACILITY: SFR PROPOSED DESIGN FLOW (.1949): 480 gpd PROPERTY SIZE: _____

LOCATION OF SITE: Lot 1 Sarahs Creek PROPERTY RECORDED: _____

WATER SUPPLY: ☒ Private ☐ Public ☒ Well ☐ Spring ☐ Other _____

EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut

TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	5% +- S/L	0-9	gr wk sbk fr vsl	fr sss p					.3
		9-27	wk-m sbk RC	fr s p sep					
		27-43	wk f sbk y pc	fr sss p few vf sap					
		43-60	LSap	fr sss p few vf sap w rock					
2	Recent Area	0-21	wk f sbk brn sl cl vsl sch	fr sss p					.25
		21-49	wk-m f sbk RC	fi-fr s p sep					
		49-60 (BC)	wk f sbk mpc l	fr sss p common vf sap					
		60-67	Marine L/fsl Sap						
3		0-4	wk f sbk brn sl cl	fr sss p					.3
		4-24	m f sbk RCL	fr sss p sep					
		24-62	wk f sbk/sbk vfr LSap Marine	fr sss p					
4		0-2	gr brn sl cl	fr sss p					.3
		2-18	m f sbk CL	fr-fi sss p sep					
		18-41	wk f sbk brn CL	fr sss p					
		41-60	Marine LSap	fr-fi sss p					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	45	45
System Type(s)	Gravity 25% Red.	Gravity Up 25-50% Red.
Site LTAR	.3	.25-.3

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): 45

EVALUATED BY: _____

OTHER(S) PRESENT: _____

COMMENTS: _____