ON-SITE WASTEWATER SECTION

COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Russ Graham APPLICATION DATE _____

ADDRESS: _____ DATE EVALUATED: 9-15-03

PROPOSED FACILITY: SFR PROPOSED DESIGN FLOW (.1949): 360 gpd PROPERTY SIZE: _____

LOCATION OF SITE: Lot 8 Sarahs Creek PROPERTY RECORDED: _____

WATER SUPPLY: ~~Private~~ Public ~~Well~~ Spring Other _____

EVALUATION METHOD: Auger Boring ~~Pit~~ Cut

TYPE OF WASTEWATER: ~~Sewage~~ Industrial Process Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-9	gr-wksbk/gr sl fr sss p						.25
		9-26	wk-mtsbk RC fr sp	Fe-mn concretions coatings					
		26-37	wkbk yp cl	fr sss p	Fe-mn coatings in upper horizon few common mn/sap				
2	6%± S/L	0-15	wkfsbk brn sl	fr sss p					.25-.3
		15-38	wkfsbk RC	fr sp/ss p					
		38-60	wkfsbk/sbk yp cl	fr ss p	few common mn/sap				
3		0-12	gr-wksbk brn sl	fr ss p					.25-.3
		12-35/40	wkfsbk RC	fr sp ss p					
		35/40-65 (Bc)	wk-fsbk-massive yp cl	fr ss p	common mn w. rock and sap				
			wavy boundary						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	GRAV 25% Red	LPP/RDS
Site LTAR	.25	.25

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): PS

EVALUATED BY: [signature]

OTHER(S) PRESENT: _____

COMMENTS: _____