DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: Russ Fairbanks APPLICATION DATE _____
ADDRESS: _____
PROPOSED FACILITY: SFR PROPOSED DESIGN FLOW (.1949): 360gpd DATE EVALUATED: 9-15-03
LOCATION OF SITE: Lot 10 Sandbar Creek PROPERTY SIZE: _____
PROPERTY RECORDED: _____
WATER SUPPLY: ~~Private~~ ☐ Public ~~Well~~ ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ~~Pit~~ ☐ Cut
TYPE OF WASTEWATER: ~~Sewage~~ ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 5% ± S | 0-10 | comp fill scl/cL | vfi | | | | | .25 > 10" |
| | | 10-22 | mfsbk R-brn | cl fr sssp | | | | | |
| | | 22-52 | MKfsbk RC | fi sp sepo | | | | | |
| | | 52-68 | wkfsbk yr cl | fr sss p common mid sap | | | | | |
| | | | | | | | | | |
| 2 | | 0-10 | wk fsbk brn-rbrn scl | fr sss p | | | | | .25-.3 |
| | | 10-45 | mfsbk RC | fi-fr sp sepo | | | | | |
| | | 45-68 | wkfsbk yr cl | fr sss p few mid sap | | | | | |
| | | | | | | | | | |
| | | | slomp mat'l | | | | | | |
| 3 | | 0-7 | wkfsbk brn scl | fi sss p | | | | | .25 |
| | | 7-14 | wk fsbk brn-rbrn sc | fr sp sepo | | | | | |
| | | 14-33 | wk-mksbk RC | fr sp sepo | | | | | |
| | | 33-63 | wkfsbk yr cl | fi-fr sss p | | | | | |
| | | | | | | | | | |
| 4 | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | PS | RS |
| System Type(s) | Conv 25% Red | Conv 25% Red |
| Site LTAR | .25 | .25 |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): RS
EVALUATED BY: DHH
OTHER(S) PRESENT: _____

COMMENTS: _____