VISION OF ENVIRONMENTAL HEALTH:
I-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

WNER: David Beard APPLICANT: _____
DDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 12-3-00
OPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): 480 gpd PROPERTY SIZE: _____
CATION OF SITE: Honeycutt Rd - across from Lomac Metals PROPERTY RECORDED: _____
ATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
'ALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut use 1000 gal tank
PE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed 41 Erosion 155'

.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-6	gr wk fsbk fsl	vfr					PS .3
	6-16	SAB	vfr sl sticky					
	16-46	mod fsbk SiL	fi vfr sl sticky	bed rock appears at this depth				
	0-10	gr wk fsbk	fri sl sticky/sl pl					PS .3
	10-48	SAB	fri sl sticky/sl pl	bed rock appears at this depth				
	0-46	mod fsbk	friable sl sticky/sl pl	bed rock appears at this depth				PS .3 Erosion
		Hole stopped due to bed rock						
	0-54	mod fsbk	fri sl sticky/sl pl	bed rock appears at this depth				PS .3 Erosion
		Hole stopped due to bed rock						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ailable Space (.1945)		
tem Type(s)		
: LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____