SOIL/SITE EVALUATION

(Continuation Sheet)

Sheet ____ of ____

DEPARTMENT OF ENVIRONMENT
AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

PROPERTY ID #: _____
DATE OF EVALUATION: _____
COUNTY: _____

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
P:t 5	3-5%	0-10	Brsl wsbk	Frsssp	YBS 34"-42"	55"	Few Inc Sap	-	PS 0.25
		10-42	Rc sbk	Frsssp					
		42-55	R-l wsbk	Frsssp					
P:t 6	3-5%	0-8	Brsl wsbk	Frsssp	YBS 44"	60"	Few Inc Sap 40"	-	PS 0.25 0.13
		8-44	Rc sbk	Frsssp					
		44-60	Rc wsbk	Frsssp					
P:t 7	3-5%	0-8	Brsl wsbk	Frsssp	Few YBS @ 42"	50"	-	-	PS 0.25 - 0.275
		8-56	Bc Rc sbk	Frsssp					
P:t 8	3-5%	0-12	Brsl wsbk	Frsssp	Few YBS 38"-48"	58"	-	-	PS 0.25 - 0.275
		12-48	Rc sbk	Frsssp					
		48-58	Rc wsbk	Frsssp					
P:t 9	3-5%	0-9	Brsl wsbk	Frsssp	-	60"	Few Inc Sap 42"	-	PS 0.3
		9-46	Rc sbk	Frsssp					
		46-60	Rc wsbk	Frsssp					

COMMENTS: _____

DENR/DEH

ON-SITE WASTEWATER SECTION

Sheet ____ *of* ____
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Heath Campbell _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: _____
PROPOSED FACILITY: 3 bedroom PROPOSED DESIGN FLOW (.1949): 360 gpd PROPERTY SIZE: 0.589 Ac
LOCATION OF SITE: Anchor Ln - Captain's Cove #10 PROPERTY RECORDED: _____
WATER SUPPLY: •X Private • Public •X Well • Spring • Other _____
EVALUATION METHOD: •X Auger Boring • Pit • Cut TYPE OF WASTEWATER: •X Sewage • Industrial Process • Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	AC #9 LS 10-12%	0-8	Br SL Gr	V.Fri SS/SP	Few 4-B3	45"+	-		PS .275
		8-14	Red SCL w/Br	Fri SS/SP					
		14-45	Red Cly SBk	Fri SS/SP					
		@45	Floater						
2	AB #10 LS 5-8	0-12	Br SL Gr	V.Fri SS/SP	V.Few 4-B	48"	-	-	PS .3
		12-48	Red Cly SBk	Fri SS/SP					
3	AB #11 LS 5-6%	0-11	Br SL Gr	V.Fri SS/SP	Few 4-B	36"	-		PS .25
		11-36	Red Cly SBk	Fri SS/SP					
		@36"	Floater/Quartz						
4	AB #12 LS 4-5%	0-11	Br SL Gr	Fri SS/SP	Few 4-B3		-		PS .25
		11-40	Red Cly SBk	Fri SS/SP					
		40-42	Red SCL w/Br	Fri SS/SP					
		@42"	Floater/Quartz						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	438 F42	438F42
System Type(s)	PPBPS	PPBPS
Site LTAR	0.275	0.225

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: GM + MA
OTHER(S) PRESENT: _____

COMMENTS: _____

SOIL/SITE EVALUATION

(Continuation Sheet)

Sheet ____ *of* ____

DEPARTMENT OF ENVIRONMENT
AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

PROPERTY ID #: ____________
DATE OF EVALUATION: ____________
COUNTY: ____________

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941)		OTHER PROFILE FACTORS				PROFILE CLASS & LTAR
			.1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	.1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	
AB 13	LS 3-5%	0-16	BtRscl wsbk	FISSSP	-	48"	[illegible] 35"	—	PS 0.3
		16-42	Rc sbk	FISSSP					
		42-48	Rcl wsbk	FISSSP					

COMMENTS: ____