N-SITE WASTEWATER

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

4730-4

OWNER: C & S ASSOCIATES APPLICANT: GINGER CECIL

ADDRESS: 904 SALEM ST, THOMASVILLE APPLICATION DATE: 8/18-98 DATE EVALUATED: _____

PROPOSED FACILITY: 3BR H/C.S. PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: 15,866.45 SF

LOCATION OF SITE: MEADOW GLEN #19 PROPERTY RECORDED: _____

WATER SUPPLY: ☐ Private ☑ Public ☐ Well ☐ Spring ☐ Other _____

EVALUATION METHOD: ☑ Auger Boring ☑ Pit ☐ Cut

TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL. CLASS & LTAR
1	H 6% PIT	0-3	GR / SL	FR / NEXP					PS 0.25
		3-8	MMSBK / CL	FR-S / NEXP					
		8-20	MMSBK / C	FR-SS / NEXP					
		20-45	WMABK / MICACEOUS C	FR-SS / NEXP					
		45-48	WFSBK / MICACEOUS SIC	FR / NEXP					
2	H 8%	0-5	GR / SL	FR / NEXP					PS 0.25
		5-16	MMSBK / CL	FR-S/SP / NEXP					
		16-48	WMSBK WMABK / C	FR-SS/SP / NEXP					
3	H 9%	0-4	GR / SL	FR / NEXP					PS 0.25
		4-15	~~SBK~~ MMSBK / CL	FR-S/SP / NEXP					
		15-48	WMABK / C	FR-SS/SP / NEXP					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	III	III
[illegible]	0.25	0.25

OTHER FACTORS (.1946): NONE (DRAINAGE)

SITE CLASSIFICATION (.1948): PS

EVALUATED BY: S. HEDRICK

OTHER(S) PRESENT: _____