DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 12-22-00
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 69 Meadowview PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-10	wksab brnsl fr ssp						P .3
		10-23/30	SAB R/T	fri ssp					
		23/30- 55	(BC) marine LSAP	fi fr ssp					
2		0-8	wksab brnsl fr ssp						P .3
		8-35	SAB RCL	fr ssp SEXP					
		35-61	wksab/pebble ye cl/l	fri sand m mBpp fr ssp					
3		0-21	wksab brnsl fr ssp						P .3
		21-48	wksab-bk RCL	fr ssp					
4	AH 7-12-01 left rear of lot where dwelling stood	0-6	Saturated Temporarily Comprised brn	scl fi ssp					.3 >12"
		6-16	Saturated Temporarily Comprised 10 12"	sl/RC fR ssp SEXP					
		16-31	wksab RCL	fr ssp SEXP				36 48 Thin	
		31-50	wksab R-yRL	fr ssp few mica flakes					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____