VISION OF ENVIRONMENTAL HEALTH:
-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 12-6-00
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 79 phase 4 Meadowlow PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed D C "Dig slope

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-5	gr sl/sh/vfr	L-fr					5 .3
	5-26	SAB sl/fr/fr	fr ss sp ssp/sv					
	26-51	L sap // L common mi sap		fr ss sp	fr sl fr			
					Pit could be deeper			
	0-6	w/ sh/ pw sl/sl/fr						5 .5
	6-20	SAB pr/sl/fr	fr ss sp ssp/sv	L ss sp	fr ss sp			
	20-37	w/ AB/sh/pl-fr	pl-fr common					
	37-50	L/sl sp/fr	fr ss sp		Pit could be deeper			
	0-3	brn sl/sl/fr						probably .3
	3-16	SAB sl/fr	fr ss sp ssp/sv					
	16-51	w/ AB/sh-pw mi	L sap fi-fr ss sp	fr ss sp	Restrictive pan			

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ailable Space (.1945)		
stem Type(s)		
: LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____