VISION OF ENVIRONMENTAL HEALTH:
I-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

WNER: _____ APPLICANT: _____
DDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 10-17-01
OPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
OCATION OF SITE: Lot 63 phase 4 Rivercrest Glen PROPERTY RECORDED: _____
ATER SUPPLY: ☐ Private ☑ Public ☐ Well ☐ Spring ☐ Other _____
ALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
PE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
Pit (1)	0-6	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]		.3
	6-60	[illegible]	[illegible]					
Pit (2)	0-9	[illegible]	[illegible]	[illegible]	[illegible]			.3
	9-30	[illegible]	[illegible]					
	30-52	[illegible]	[illegible]					
Pit (3)	0-12	[illegible]	[illegible]	[illegible]	[illegible]			.3
	12-54	[illegible]	[illegible]					
	54-66	[illegible]	[illegible]					
Pit (4)	0-35	[illegible]	[illegible]	[illegible]	[illegible]			.3
	35-42	[illegible]	[illegible]					
	42-57	[illegible]	[illegible]					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ilable Space (.1945)		
em Type(s)		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____