DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: C&S Assoc / Tom Pearis APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
PROPOSED FACILITY: SFR PROPOSED DESIGN FLOW (.1949): 360gpd PROPERTY SIZE: _____
LOCATION OF SITE: Lot 110 Meadow Glen PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☑ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	LSS 14%	0-24	Fill						(e) 0-24" .4 e 24"
		24-52	SL SAP Mass	fi vSNP sap	inc. of cl	—	PS	—	
2	LSS 18%	0-18	Fill						.4 e 18"
		18-52	SL SAP Mass	fi vSNP sap	cl Inc				
3	LSS 14% 22%	0-12	Bsk lvl	fi SSSP					PS 13 to 48"
		12-48	Rck wSAP	fi SSSP - SAP Inc.					
		48-60	w/Rock w SAP	Inc.					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS per 1956	PS per 1956
System Type(s)	GRW PPBRS	GRW PPBRS
Site LTAR	.3	.3

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): Revised plot barely PS
EVALUATED BY: Shady Freeman ; Reviewed by [illegible] 6-28-06
OTHER(S) PRESENT: _____
Fill material removed from drainfield area