DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: DPG Properties, LLC — APPLICATION DATE: ___
ADDRESS: ___ — DATE EVALUATED: ___
PROPOSED FACILITY: 3 BR SFD — PROPOSED DESIGN FLOW (.1949): 360 GPD — PROPERTY SIZE: ___
LOCATION OF SITE: LOT 114 Meadow Glen Subdivision — PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☒ Auger Boring ☒ Pit ☐ Cut — TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1948 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRIC CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	#14	0-18	Mo, Sbk, C	Fr, SS, SP					>18" 0.40
		18-36	WK, Sbk, CL	Fr, SS, SP wy	F-C Sap, Dnclus,				
		36-58	Mass., L-Sap	Fr, SS, SP wy	F-CL Pockets				
2	#111	0-10	WK, Sbk, SL/CL	Fr, SS, SP					0.275 - 0.30
		10-35	Mo/WK, Sbk, SL/C	Fr, SS, SP W	F-Brwn (Mtn)				
		35-50	WK, Sbk, C	Fr, SS, SP W	C-Sap, Dnclus,				
	#13	0-23	Mo, Sbk C	Fr, SS, SP					<23" 0.30
		23-40	Mo/WK, Sbk, CL	Fr, SS, SP wy	F-Sap. Dnclus,				>23" 0.35 - 0.40
		40-55	Mass., L-Sap.	Fr, SS, SP W	F-CL Pockets				
	Auger #4	0-3	WK, Gr, SL	VFr, SS, NP					0.30
		3-18	Mo, Sbk, C	Fr, SS, SP					
		18-30	WK, Sbk, CL	Fr, SS, SP wA	F-Sap				
		30-48	WK, Sbk, CL	Fr, SS, SP wA	C-M Sap.				

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ilable Space (.1945)		
tem Type(s)		
LTAR		

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___

MENTS: