SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Attn: Patrick

ER: Co's Assoc APPLICANT:
DRESS: APPLICATION DATE: DATE EVALUATED: 12-18-02
POSED FACILITY: PROPOSED DESIGN FLOW (.1949): 360 gpd PROPERTY SIZE:
ATION OF SITE: Lot 143 pl 4 Meadow Glen PROPERTY RECORDED:
ER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other
LUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
E OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
(1)	0-6	gr-wk sbk brn sl/l sl/l fr						PS .3
	6-20	sbk rck	fr ss sp					
	20-68	wk-str pris-mass rock ls sp	ss/l common mi sap					
(2)	0-6	wk sbk brn-pl brn sl/l fr						PS .3
	6-34	str sbk rc	fr ss sp sap					
	34-70	wk-str pris chky	common mi sap fr ss sp					
(3)	0-8	gr-wk sbk brn-pl brn sl/l fr						PS .3
	8-44	wk-str sbk l/l	fr ss sp - common mi sap					
	44-72	wk-str mass ls sap	carbonate fr ss sp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
able Space (.1945)		
n Type(s)		

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948):
EVALUATED BY: DLA
OTHER(S) PRESENT: