DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ____ of _
PROPERTY ID #:
COUNTY: IREDELL

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM 4730 486343 (PT)

OWNER: C & S Assoc. LLC APPLICANT: GINGER CECIL
ADDRESS: 904 SALEM ST. THOMASVILLE NC APPLICATION DATE: 8-18-98 DATE EVALUATED: ____
PROPOSED FACILITY: 3BR H w/cs PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: 23,169.23 SF
LOCATION OF SITE: MEADOW GLEN # 22 PROPERTY RECORDED: ____
WATER SUPPLY: ☐ Private ☑ Public ☐ Well ☐ Spring ☐ Other ____
EVALUATION METHOD: ☑ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL. CLASS & LTAR
1	L 8% PIT	0-5	GR / SCL	VFR / NEXP					PS 0.25
		5-9	MMSBK / CL	FR-S / NEXP					
		9-22	MMSBK / C	FI-SS/SP/ NEXP					
		22-48	WMABK / MICACEOUS SIC	FR / NEXP					
2	L 8%	0.5	GR / SCL	VFR / NEXP					PS 0.25
		5-10	MMSBK / CL	FR-SS / NEXP					
		10-25	SBK / C	FI-S/SP/NEXP					
		25-45*	ABK/SBK/ MICACEOUS SIC	FR / NEXP					
		45"Rock	ROCK						
3	L 8%	0-4	GR / CL	VFR / NEXP					PS 0.25
		4-20	~~ABK~~ / C	FR-SS/SP/NEXP					
		20-48	SBK/ABK/ CL	FR-SS/SP/NEXP					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	AS	AS
System Type(s)	III	III
Site LTAR	0.25	0.25

OTHER FACTORS (.1946): GULLIED
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: S. HENDRICK
OTHER(S) PRESENT: LOREN COOK