VISION OF ENVIRONMENTAL HEALTH:
I-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Space problems - need Repair Syst - 60S to right of lot

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 11-21-00
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 151 Mason Cove PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

11-30-00 Rec'd Written Approval
P 6 on Pits 0-14 gr brn SL/sil fr sap; 14-18 wtrd gr brn SCL fr sap

	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-8	gr brn sL/ sol fr						P5 .25 23" 3
		8-35	blky brn/SCL fr						23"
		35-56	bgy brn wtrd/gr - marine brn SL fr						35"
2		0-10	gr brn sl/sol fr sap						.25
		10-28	gr brn/gy brn/SCL fr/sl sap						.2
		28-50	bgy brn/gy brn - marine brn/SCL fr-vfr sp-mp sap						
3		0-13	brn/dk brn/clay SCL fr sap						.3 .25
		13-43	brn/gy brn SiCL fr sap						
		43-54	gy brn/gy brn/clay SCL fr sap						
4	R-600	0-6	brn/dk brn SCL fr						P3 .3
		6-49	gy brn/gy SCL fr sap						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Size/LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____