DENR/DEH

ON-SITE WASTEWATER SECTION

Sheet 1 of 2
PROPERTY ID #:
COUNTY:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Anaheim Homes
ADDRESS:
APPLICATION DATE
DATE EVALUATED:
PROPOSED FACILITY: 4 bedroom PROPOSED DESIGN FLOW (.1949): 480 gpd
PROPERTY SIZE: 0.667 ac
LOCATION OF SITE: Winding Forest Lot 41
PROPERTY RECORDED:
WATER SUPPLY: • Private • X Public • X Well • Spring • Other
EVALUATION METHOD: X Auger Boring • Pit • Cut
TYPE OF WASTEWATER: X Sewage • Industrial Process • Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941)		OTHER PROFILE FACTORS				PROFILE CLASS & LTAR
			.1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	.1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	
1	LS 5-7%	0-3	Br s/ gr	Frss p	Few-common Mottles @ 26"	48"	—	—	PS 0.225
		3-10	RBr-scl wsbk	Frss p					
		10-48	Rc sbk	F-Frss p					
2	LS 5-7%	0-5	Br s/ wsbk	Frss p	—	48"	Few Inc. Sap	—	PS 0.3
		5-40	Rsc sbk	Frss p					
		40-48	Rscl wsbk	Frss p					
3	LS 5-7%	0-5	RBrscl wsbk	Frss p	Very Few Very faint Drainage Mottles 30-38"	48"	Inc Sap @ 38"	—	PS 0.3-0.275
		5-38	Rsc sbk	Frss p					
		38-48	Rscl wsbk	Frss p					
4	LS 5-7%	0-3	Br s/ gr	Frss p	—	48"	Few Sap Inc @ 22"	—	PS 0.3
		3-34	Rc sbk	Frss p					
		34-48	Rcl wsbk	Frss p					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948):
EVALUATED BY:
OTHER(S) PRESENT:

COMMENTS:

DENR/DEH

ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Anaheim Homes
ADDRESS: ___
APPLICATION DATE ___
DATE EVALUATED: ___
PROPOSED FACILITY: 4 bedrooms PROPOSED DESIGN FLOW (.1949): 480 gpd
PROPERTY SIZE: 0.66 ± Ac
LOCATION OF SITE: Winding Forest Lot 41
PROPERTY RECORDED: ___
WATER SUPPLY: • Private • X Public • Well • Spring • Other ___
EVALUATION METHOD: • X Auger Boring • Pit • Cut
TYPE OF WASTEWATER: X Sewage • Industrial Process • Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
5	LS 5-7%	0-6	Brsc/wsbk	Frs ssp	—	48"	—	—	PS 0.3
		6-35	Rc sbk	Frsssp					
		35-48	Rc/wsbk	Frsssp					
6	LS 5-7%	0-5	Brsc/wsbk	Frsssp	—	48"	Few Inc Sap @ 30"	—	PS 0.3
		5-32	Rc sbk	Frsssp					
		32-48	Rc/wsbk	Frsssp					
7	LS 5-7%	0-5	Brsc/wsbk	Frsssp	Few YB's + Mn to 38" No mottles after 38"	48"	—	—	PS 0.25
		5-40	Rc sbk	Frsssp					
		40-48	Rc/wsbk	Frsssp					
8	LS 5-7%	0-3	Brsc/wsbk	Frsssp	—	48"	Few Sap @ 38"	—	PS 0.3
		3-48	Rc sbk	Frsssp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	640 Ft²	540 Ft²
System Type(s)	PPBPS	PPBPS
Site LTAR	0.25	0.3

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: GM & MA
OTHER(S) PRESENT: ___

COMMENTS: ___