DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: William Tunstall APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3-5-05
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Robin Crest PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-3"	Brw SCL	GR FR	m-w SBK SS, SP, SE Fi-FR Mica Flakes				PS .3
		3"-38"	Rd to Rd/Brw CL	Common					
			> 24"						
		>38'	Hitting something hard, couldn't auger through						
2		0-8"	Brw SCL	GR FR	m-w SBK SS, SP, SE, FI-FR SS, SP, SE, FR w/ Few yellow brown mott				PS .3
		8-38"	Rd/Brw to Rd CL						
		38-40"	Rd/Brw CL	w/SBK Common Mica Flakes &					
3		0-4"	Brw SCL	GR FR	m-w SBK SS, SP, SE FI-FR SS, SP, SE, FR				PS .3
		4"-30"	Rd/Brw CL						
		30-45"	Rd/Brw to Hell/Brw CL w/Few to Many SAP Indiv						
		45"	SAP						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____