DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Clayton Homes
ADDRESS: _____ APPLICATION DATE _____
PROPOSED FACILITY: Mobile Home PROPOSED DESIGN FLOW (.1949): 360 gpd DATE EVALUATED: 5-15-06
LOCATION OF SITE: Talley Rd & Clayton Farm Rd PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☒ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	3-4%	0-8	lsbk cl			48			PS .3
		8-29	lsbk c	fr ss/sp se					
		29-45	lsbk cl						
		45-48	cl+sap						
2		0-48	lsbk cl+sap (51)	fr ss/sp se		48			PS .3
		% sap increases w/ depth							
3		0-15	lsbk cl			48			PS .3
		15-30	lsbk c	fr ss/sp se					
		30-48	lsbk cl						
			inc. sap						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	YES	YES
System Type(s)	25% red	25% red.
Site LTAR	.3	.3

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: J. Melville
OTHER(S) PRESENT: _____

COMMENTS: _____