SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: DONALD & JANE STRAUSS OWNER: ✓ AGENT: PHONE: 876-0324
ADDRESS: 213 BAYMONT DR. APPLICATION DATE: 3-11-97 DATE EVALUATED: 4-4-97
STUL NC 28677 PROPOSED FACILITY: 3BR HOUSE W/ BASEMENT
PROPERTY SIZE: 12.503 AC
LOCATION OF SITE: WALLACE SPRINGS RD, TR WOODFIELD DR, ON (R) ~[redacted] 0.25 MI, 500' BACK
WATER SUPPLY: On-Site Well ✓ Comm. Well Public Other EVAL. METHOD: Auger Boring ✓ Pit Cu

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1957/ 1966 SAPRLT CLASS.	HORIZ LTAR
1	L ~8%	0-42	SBK / c-cL	1:1 / FR	—	—	PS	PS	0.3
		42-48	GR / sic/SAP.	1:1 / FR					
2	L ~8%	0-42	SBK / c-cL	1:1 / FR	—	—	PS	PS	0.3
		42-48	GR / sic/SAP	1:1 / FR					
3									
4									
5									

AVAILABLE SPACE (.1943): S SITE CLASSIFICATION (.1948): PS SITE LONG-TERM ACCEPTANCE RATE: 0.3
EVALUATED BY: S HEDRICK OTHER(S) PRESENT: JANE STRAUSS
COMMENTS: