IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System — G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Ray Russell DATE 5/14/75 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 115 N. - T.R. on Sigmon Dr. at Shadell Oil Co. - 1st house on left

S. R. No. _____


SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms _____ No. Bathrooms _____

Garbage Disposal Unit	Yes (✓)	No ( )	Character & Porosity of Soil	_____
Auto. Dishwasher	Yes ( )	No ( )	Percolation Rate	_____
Auto. Wash. Machine	Repair ( )	No ( )	Topography	Repair
Site Suitable	Yes ( )	No ( )	Depth to Water Table	_____
			Rock or other impervious formations	_____

Lot Area _____



Plot of System

Size of Tank Existing Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 375 Linear Ft. 150

Depth of Stone in Lines 10"

Water Supply: Individual (✓)

Public ( )

Installed by Bobby Beattie

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Andrew E. Conway DATE 5/14/75

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold