IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Gaither Bldg. Co. DATE 8-1-74 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION NE corner Chestnut St. + Cameron Dr Beverly Heights

S. R. No. _____

SUBDIVISION NAME Beverly Heights LOT NO. 170 SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Character & Porosity of Soil Red Clay
Percolation Rate _____
Topography Slight Slope to Front
Depth to Water Table _____
Rock or other impervious formations None

Lot Area 14,500



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 624 Linear Ft. 250
Depth of Stone in Lines 10"
Water Supply: Individual ( )
Public (✓)

Installed by Gaither Bldg. Co.

IMPROVEMENTS PERMIT BY _____

COMMENTS: Nitrification line shallow near end of lines.

CERTIFICATE OF COMPLETION BY Glenn A. Jr. DATE 8/1/74

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold