## IREDELL COUNTY HEALTH DEPARTMENT

### (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System — G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Gaither Bldg. Co. DATE 9-8-76 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Beverly Dr. _____ S. R. No. _____


SUBDIVISION NAME Beverly Heights LOT NO. 154 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 1½ ✓

| | | | | | |
|---|---|---|---|---|---|
| Garbage Disposal Unit | Yes ( ) | No (✓) | Character & Porosity of Soil | Clay | |
| Auto. Dishwasher | Yes (✓) | No ( ) | Percolation Rate | 60 | |
| Auto. Wash. Machine | Yes (✓) | No ( ) | Topography | Slight Slope to left side | |
| Site Suitable | Yes (✓) | No ( ) | Depth to Water Table | none | |
| | | | Rock or other impervious formations | none | |

Lot Area 110 X 163 ft




Plot of System

Size of Tank 1250 Gals.
Nitrification Field:
No. of Lines 5
Sq. Ft. 621 Linear Ft. 250
Depth of Stone in Lines 10"
Water Supply: Individual ( )
Public (✓)

Installed by Gaither Bldg. Co.

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF COMPLETION BY _____ DATE 9/8/76

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold