# IREDELL COUNTY HEALTH DEPARTMENT

## (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Hope Bro DATE 3-18-76 PERMIT NO. _____

PHONE: Business _____ Home _____


LOCATION Chipley Park

SUBDIVISION NAME _____ LOT NO. 19 SECTION OR BLOCK NO. _____ S. R. No. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

| | | | | |
|---|---|---|---|---|
| Garbage Disposal Unit | Yes ( ) | No (✓) | Character & Porosity of Soil | Red Clay |
| Auto. Dishwasher | Yes ( ) | No (✓) | Percolation Rate | |
| Auto. Wash. Machine | Yes (✓) | No ( ) | Topography | Slope to back |
| Site Suitable | Yes (✓) | No ( ) | Depth to Water Table | Low |
| Lot Area 20,000 Sq ft. | | | Rock or other impervious formations | None |




Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 625 Linear Ft. 250
Depth of Stone in Lines 10"

Water Supply: Individual ( )
Public (✓)

Installed by Hope Bro

IMPROVEMENTS PERMIT BY _____

COMMENTS: Important that downspouts be diverted away from Tank and lines.

CERTIFICATE OF COMPLETION BY E. A. Stevenson DATE 3-18-76

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold