DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Jack Borders APPLICANT: Same
ADDRESS: Rhea Farm Rd, City APPLICATION DATE: 10/14 DATE EVALUATED: 11/14
PROPOSED FACILITY: 3BR House Lot PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: _____
LOCATION OF SITE: Willow Brook #13 PROPERTY RECORDED: Yes
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed
Willow Brook #13

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL CLASS & LTAF
1	Linear	0-7	sl Sbk	fi ss sp SEXP	DRK BRN				PS
		7-40	c Abk	fi s p SEXP	red BRN				.25
		40-48	sl Sbk	fi/fr ss sp SEXP					
2	Linear	0-6	cl Sbk	fi/fr ss sp					PS
		6-40	c Abk	fi s p SEXP					.25
		40-48	sl sap Sbk	fi/fr ss sp SEXP					
3	Repair	0-10	cl Sbk	fi/fr ss sp SEXP					PS
		10-21	sl Abk	fi s p SEXP					.25
		21-48	sl sap Sbk	fi/fr ss sp SEXP					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)		
Site LTAR	.25	.25

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: Bill Suggs
OTHER(S) PRESENT: _____