ISION OF ENVIRONMENTAL HEALTH:

PROPERTY ID #: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

ER: _____ APPLICANT: _____

DRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____

POSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

CATION OF SITE: Lot 7 Chimney Ridge PROPERTY RECORDED: _____

TER SUPPLY: ☐ Private ☐ Public ☐ Well ☑ Spring ☐ Other _____

LUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

E OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | OTHER PROFILE FACTORS .1943 SOIL DEPTH | OTHER PROFILE FACTORS .1956 SAPRO CLASS | OTHER PROFILE FACTORS .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|
| | 0-8 | BSCL GR | FR | | | | | PS |
| | 8-23 | RC | FI SP | | | | | |
| | 23-5x | RL mf-vf | FRI SOft | | | | | 25 |
| | | | | | | | | 3 |
| | | | | | | | | |
| | 0-10 | BSCL GR | FR SSP | | | | | PS |
| | 10-2x | RL | FI SP | | | | | |
| | 2x(+) | RLL mf-vf | FR SPL | | | | | 3 |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| able Space (.1945) | | |
| m Type(s) | | |

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____