DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 6-27-97
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 25 Ridgecrest (revisit) PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1	L ~4%	0-25	SaLo rc/cl	fr sp sss p se/p					PS .3 @ L-36
		25-36	wk sbk to less rcl w/ many incl sap/wr						
		36-48	SAP/WR mix						
2		0-17	SaLo rc/cl	fr sp se/p - sss p					
		17-36	wk sbk to R light OL w/ incl sap/wr/cobble						
		36-48	platy (grus when crushed) wr/sl sap	fr ss-ns/p					
3		0-19	SaLo R cl	fr sss p se/p					
		19-48	many rock/wr-sap cl mix						
		more soil depth on left side of pit							
4	LS 4-6%	0-36	SaLo rcd/cl	fr sss p se/p few incl sap/wr					PS .3 @ L-36+
		36-55	SAP/WR-mix						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

#5 LS 4-6% 0-54 - m-wk sbk rcl few incl sap/wr fr - fi sss p se/p PS .3+