DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED 6-27-97
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 26 Ridgecrest (revised) PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ	PROFILE CLASS & LTAR
1	SS 48%	0-36	sl-wk sbk rc/cl	fr sp sss ps exp few incl sap					PS .3 @ ≤ 36"
		36-55	wk sbk str less l/sl sap	fr ss-ns sp					
			appears to be usable sap						
2	SS 6-10%	0-28	sl sbk rcl	fr sp-sss ps exp					PS .3 @ ≤ 40"
		28-40/48	wk sbk rcl w incl sap						
		40/48-56	rock/sap mix						
3	SS 6-10%	0-40	sbk rcl	fr sp-sss p incl Rock/WR					PS .3 @ ≤ 40"
		40-57	gr sl sap	fr					
			good sap but greater than 36"						
4	SS 6-10%	0-19	gr-sbk rbr sicl	fr					PS .3 @ ≤ 43"
		19-43	sbk rc/cl	fr-fi sp sss ps exp					
		43-56	WR/sap mix						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

#5 SS 8-12% 0-36 sbk rc/cl few incl Rock/scattered rock /// 36-48 sl sap/WR mix