IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System — G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR John Redmon Jr. DATE 11-14-73 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Out Chipley Ford Rd. Go approx 1½ miles East Smith White Store. Brick House on Left S. R. No. 1907


SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 3

Garbage Disposal Unit: Yes (✓) No ( )
Auto. Dishwasher: Yes (✓) No ( )
Auto. Wash. Machine: Yes (✓) No ( )
Site Suitable: Yes (✓) No ( )
Lot Area Acreage

Character & Porosity of Soil Red Clay
Percolation Rate NC Perk Test Made
Topography Sloping to back and side
Depth to Water Table Low
Rock or other impervious formations Rock Hit in Tank Hole



Plot of System

Size of Tank 1250 Gals.
Nitrification Field:
No. of Lines 4
Sq. Ft. 750 Linear Ft. 300
Depth of Stone in Lines _____
Water Supply: Individual (✓)
Public ( )

Installed by Harlie Lackey
Allie Robertson Bldr.

IMPROVEMENTS PERMIT BY _____

COMMENTS: House was under Construction Prior to Oct 1, 1973
No improvements Permit or septic tank layout made.

CERTIFICATE OF COMPLETION BY E. A. Stevenson DATE 11-14-73

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold