DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Mrs Spear
ADDRESS: _____
APPLICANT: _____
APPLICATION DATE: _____
DATE EVALUATED: 4-22-2
PROPOSED FACILITY: SFR
PROPOSED DESIGN FLOW (.1949): 360 gpd
PROPERTY SIZE: _____
LOCATION OF SITE: Lot 57 Tenby Cove
PROPERTY RECORDED: _____
WATER SUPPLY: ☑ Private ☐ Public / ☑ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 4-6% S mod drained	0-4	gr-sl/l	fr					0.37
		4-27	sbk rc	fr sp fl					
		27-54	sbk rc	fr sp fl					
2	L 4-6%	0-6	gr-sl/l	fr					0.37
		6-30	sbk rc	fr sp fl					
		30-54	sbk rc	fr sp fl					
			firm sp 45-50"						
3	L 4-6%	0-5	gr sl	fr					0.37
		5-17	sbk rc	fr sp fl					
		17-30	sbk rc	fr sp fl					
		30-54	gr sl sbk	fr vfr fl					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

4-22 Back roadside and front