DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Max Spence
ADDRESS: _____
APPLICANT: _____
APPLICATION DATE: _____
DATE EVALUATED: 4-18-96
PROPOSED FACILITY: SFR
PROPOSED DESIGN FLOW (.1949): 360 gpd
PROPERTY SIZE: 115' x 200'
LOCATION OF SITE: Lot 10 Rocky Creek
PROPERTY RECORDED: no
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L ~10% S-MOD ERODED	0-20	SaBR-hk cL	fr ss sp 1:0					.3
		20-60+	SL/fr sap	vfr ss, snp					
2	L ~10% S-MOD ERODED	0-7	brn cL	fr					.3
		7-40	mod sbk rock	fr ss sp 1:0					
		40-55+	hard w. Rock on BOTTOM, mod sbk 2 cor						
3	V ~10% S-MOD ERODED	0-3	gr brn scL	fr					.3
		3-10	wk sbk cL	fr					
		10-33	gyb dbrn cL	fr ss sp					
		33-55	Sab brn cL	vfr ss sp					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

4-7-97- Site needs to be cleaned up