DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ____
PROPERTY ID #: ____
COUNTY: ____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Mel Spare — APPLICANT: ____
ADDRESS: ____ — APPLICATION DATE: ____ — DATE EVALUATED: 4-27-96
PROPOSED FACILITY: SFR — PROPOSED DESIGN FLOW (.1949): 3 bdrm — PROPERTY SIZE: ____
LOCATION OF SITE: Lot 49, Rocky Creek — PROPERTY RECORDED: ____
WATER SUPPLY: ☑ Private ☐ Public ☑ Well ☐ Spring ☐ Other ____
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 2-5%	0-7	cl						
		7-9	sab pc	fr-5 sp fri					
		9-50	mk sab pcl	fr ss sp fri					-.3+
2	L	0-5	g. sab pbk	fr					
		5-13	sab pc	fr ss sp fri					
		13-40	mk sab pcl	fr ss sp fri					-.3
		40-48	mk sab g-R	fr ss sp fri					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ____
SITE CLASSIFICATION (.1948): Conventional Bed
EVALUATED BY: ____
OTHER(S) PRESENT: ____

Utility marked — 9-11-97 — Could not find back corners of lot

10-31-97 What a pleasant surprise — DW on site w/o permit / wait through grading / [illegible]