DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Mary Spear — APPLICANT: ___
ADDRESS: ___ — APPLICATION DATE: ___ — DATE EVALUATED: 4-17-2
PROPOSED FACILITY: ___ — PROPOSED DESIGN FLOW (.1949): 3 bdrm — PROPERTY SIZE: ___
LOCATION OF SITE: Lot 46 Kirby Creek — PROPERTY RECORDED: ___
WATER SUPPLY: ☒ Private ☐ Public ☒ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1	L 4%	0-4	sl gr sl	fr					.34
		4-10	sbk sc	fr so po					
		10-48+	m-vfsbk sc	fr ss so po					
			few gravel in matrix						
			few med faint red mot						
2	S 2-4%	0-6	gr sl	fr					.34
		6-18	sbk sc	fr ss so po					
		18-64+	m-vfsbk sc	fr ss so po					
			few gravel in matrix						
			few med faint red mot	50%					
3	S 2-4%	0-15	gr sl	fr					.34
		15-48+	sbk sc	fr ss so po					
			few gravel in matrix						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___