DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: Mark Spain — APPLICANT: _____
ADDRESS: _____ — APPLICATION DATE: _____ — DATE EVALUATED: 4-18-96
PROPOSED FACILITY: SFR — PROPOSED DESIGN FLOW (.1949): 3bdrm — PROPERTY SIZE: ~ 10 acres
LOCATION OF SITE: Lot 19, Hickory Creek — PROPERTY RECORDED: No
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | 1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) 1941 STRUCTURE/ TEXTURE | 1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR | 1943 SOIL DEPTH | 1956 SAPRO CLASS | 1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | S 4.6% | 0-14 | Sgr brn cl | fr | | | | | .34 |
| | | 14-28 | Sab R CL | fr fe sap lo | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 2 | S 16% | 0-4 | gr- brn SL/scL | fr | | | | | .34 |
| | | 4-10 | Sab RC | fr sp l.l | | | | | |
| | | 10-23 | Sab RCL | fr sc sp l.l | | | | | |
| | | 23-55+ | weathering SL sap | fr sap l.o | | | | | |
| | | | | | | | | | |
| 3 | S 4-8% Sl wood Blocks | 0-36 | Sab R brn/gr SCL | fr sap trace gravel/shale | | | | | .34 |
| | | 36-60 | weath/Sap (clay bx) | fr sap | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 4 | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____