DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet 1 of 1
PROPERTY ID #:
COUNTY: Iredell
4740201808
803

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Dina Abee
ADDRESS: lot
APPLICATION DATE 4/28/08
DATE EVALUATED: 6/7/08
PROPOSED FACILITY: 3bd
PROPOSED DESIGN FLOW (.1949): 360 gal/day
PROPERTY SIZE: 0.83 acres
LOCATION OF SITE: Beaver Rd. TR Clontz Mill, TR Ridge Creek, Tr Bootle Creek on Right
PROPERTY RECORDED: yes
WATER SUPPLY: ☐ Private ☐ Public ☑ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 2%	0-6	w, gr, SCL	Fr	Na	48"	B P.S.	None	0.3
		6-30	m, gr, C	Fr					
		30-48	m, gr, C	Fr					
		↓ w/ Sap							
2	L 1%	0-7	w, gr, SCL	Fr	Na	48"	P.S.	None	0.3
		7-28	m, gr, sbk, C	Fr					
		28-48	m, sbk, C ↓ Sap	Fr					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	P.S.	P.S.
System Type(s)		
Site LTAR	0.3	0.3

OTHER FACTORS (.1946): —
SITE CLASSIFICATION (.1948): P.S.
EVALUATED BY: [signature]
OTHER(S) PRESENT:

COMMENTS: