COUNTY: _____

SOIL EVALUATION for ON-SITE WASTEWATER SYSTEM

ER: _____ APPLICANT: _____

RESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5-22-01

OSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

ATION OF SITE: Lot 66 Wiltshire Creek PROPERTY RECORDED: _____

ER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

LUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

E OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

#5 0-12 gr brn scl fr sss sp
12-43 m-wk sab R-gr cl common infsp fr sss p
43-60 mwine gr gr L/scl sap - fewer fr sss sap .34

1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-4	brn scl	fr sss p					
	4-53	m-wk sab cl/cl	common gr brn mica infsap					.3
	0-6	wk sab brn scl	fr sss p					
	6-27	sab rock	fr sss p sap					.3
	27-55	wk f sab gr cl/L	common mica sapprox + few qtz wk fr sss p					
	0-7	gr-wf sab brn scl	fri					
old exPit	7-31	sab rock	fr sss p					.3
31-44		wk f sab gr cl/L	common mica sap fr sss p					
	0-17	gr brn scl	wise rock fr sss p					
	17-32	hard sap & rock w/ mod cl-scl			(4)			(4)
		hole stopped by BH operator						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
able Space (.1945)		
n Type(s)		
TAR		

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____