OF ENVIRONMENTAL HEALTH
ASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Mike Spear APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5-23-96
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 27 Rocky Creek PROPERTY RECORDED: _____
WATER SUPPLY: ☑ Private ☐ Public ☑ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (1941) 1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1943 RESTR. HORIZ.	PROFILE CLASS & LTAR
1	V 10-15% SLOPED	0-11	gr 4-brk sl/sl fr						.3+
		11-36	Sab R heavy cl/ light fr	fm sss p-sp 1:1					
		36-55	gradesb yr cl	fr sss pl 1:1					
			few-many fg relic mottles						
			few rock throughout horizon						
2	V 10-15% SLOPED	0-18	gr-3/b brwn sl/sl fr						.3+
		18-38	Sab R heavy cl	fr-fm sss pl					
		36-55+	sab yr cl	fr sss p 1:1					
			many fg relic mottles						
3	V 10%	0-6	gr sl	fr					.3+
		6-36	Sab R cl-few-many fg relic mottles, few in hpp						
		36-55+	gr-sdesb sl sap	fr NS, NP					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____