DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: David Wood — APPLICATION DATE: _____
ADDRESS: _____ — DATE EVALUATED: _____
PROPOSED FACILITY: _____ — PROPOSED DESIGN FLOW (.1949): 360gpd — PROPERTY SIZE: _____
LOCATION OF SITE: Wiltshire Creek Lot 21 (combined w/part of old lot 20) — PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☒ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut — TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
5	old lot 20	0-5	compacted				f-sap		.3
1b		5-32	mo sbk C	fr ss sp Red					
		32-56	wk sbk cl	fr ss sp Red					
6	old Lot 20	0-6	gr sl Br				f-C br appears sandy relic		.25 - .3
2a		6-36	mo sbk c	fr sss p					
		36-54	wk sbk cl	fr sss p					.275
7	old Lot 20	0-6	gr sl Lt Br				f-sap		.3
3		6-36	mo sbk c	fr sss p Red					
		36-53	wk/mo sbk cl	fr sss p Red					
		53-62	sl sap w/cl inclusions						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	yes	yes
System Type(s)	25% G	25% G
Site LTAR	.275	.275

COMMENTS: _____

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: T. Melville
OTHER(S) PRESENT: _____