Division of Environmental Health
On-site Wastewater Section

Property ID: 4740-48-7105
Lot #:
File #: Repair
AppID:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Owner: Jimmy Milsapps
Address: 228 Barkdale Rd Troutman, NC
Proposed Facility: Repair Design Flow (.1949) 360 GPD
Location of Site: Same
Water Supply: [ ] Public [x] Individual [x] Well [ ] Spring [ ] Other
Evaluation Method: [x] Auger Boring [ ] Pit [ ] Cut
Type of Wastewater: [x] Sewage [ ] Industrial Process [ ] Mixed

Applicant:
Date Evaluated: 12/1/2009
Property Size: 4.22 AC
Property Recorded: Yes

PROFILE #	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941 .1941 Structure/ Texture	.1941 Consistence Mineralogy	b PROFILE FACTORS .1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
AB 1	10%	0-30	C,M,SBK	SS,SP,SEXP,FR	NA/RED				
	LINEAR	30-48	CL,M,SBK	SS,SP,SEXP,VFR	NA/YR	48"	NA	NA	.3
AB 2	10%	0-27	C,M,SBK	SS,SP,SEXP,FR	NA/RED				
	LINEAR	27-49	CL,M,SBK	SS,SP,SEXP,VFR	NA/YR	49"	NA	NA	.3

Description	Initial System	Repair System
Available Space (.1945)	PS	PS
System Type(s)	Gravity 25%	Gravity 25%
Site LTAR	.3	.3

Other Factors (.1946):
Soil Evaluation By: Ben Aldridge
Others Present: Rick (A-1), Jimmy Milsapps
Site Classification (.1948): S
Site Evaluation By: Ben Aldridge
Others Present: Rick (A-1), Jimmy Milsapps