DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Robert Hedford APPLICANT: ___
ADDRESS: ___ APPLICATION DATE: ___ DATE EVALUATED: ___
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: .5 Ac
LOCATION OF SITE: Hatch - Carlyle Farms Sec 2. PROPERTY RECORDED: ___
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	T	0-8	sbk / cl	FR SS SP.					
		9-26	sbk / c	SFI SS SP					
		27-31	wkSBK / cl	SFI SS P					
		32-43	wSBK / Heavy CL	SFI SS SP					.3
		43+	weathered rock, saprolite						
2		0-18	WSBK / SCL	fr SS, SP					
		18-24	WSBK / CL	fr SS, SP					
3		0-9	sbk / scl						
		10-34	sbk / cl	FR SS SP					
		35-49	sbk / scl	FR SS MP					.3
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	Conv.	
System Type(s)		
Site LTAR	.3	

OTHER FACTORS (.1946): well location
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Sparks
OTHER(S) PRESENT: W. Ervin