~~4740613671~~

IREDELL COUNTY HEALTH DEPARTMENT 4740505674

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Marlo Corp. DATE 9-9-85 PERMIT NO. 393

PHONE: Business _____ Home _____

LOCATION Hwy 115-2 North TL 1312 TL 1313
About 3 mile on left
S. R. No. _____

SUBDIVISION NAME Carlyle Farms LOT NO. 1 SECTION OR BLOCK NO. _____


House ( ) Mobile Home (X) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (X)	Character & Porosity of Soil	Gravelly
Auto. Dishwasher	Yes ( )	No ( )	Percolation Rate	0.5 gal/ft 2/day
Auto. Wash. Machine	Yes ( )	No ( )	Topography	2-6%
Site Suitable	Yes (X)	No ( )	Depth to Water Table	4' None obs
			Rock or other impervious formations	

Lot Area EXISTING

Basement with Plumbing ~~X~~ Basement without Plumbing ~~X~~ X No Basement



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 720 Linear Ft. ~~240~~ 240
Depth of Stone in Lines 12"
Water Supply: Individual X
Public
well next door
Installed by T.J. Ervin Co.

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

~~DENIED~~

IMPROVEMENTS PERMIT BY Fred Clemmer

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Fred Clemmer DATE 9-9-85

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold