IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Marlo Corp DATE 8-26-85 PERMIT NO. 301

PHONE: Business _____ Home _____

LOCATION 21 North TL 1312 TL 1313 About 3/4 Mile on Left

S. R. No. _____

SUBDIVISION NAME Carlyle Farms LOT NO. 1 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (X) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (X)
Auto. Dishwasher Yes (X) No ( )
Auto. Wash. Machine Yes (X) No ( )
Site Suitable Yes (X) No ( )

Character & Porosity of Soil Clay
Percolation Rate 0.5 gal/ft²/day
Topography 2-4%
Depth to Water Table _____
Rock or other impervious formations NONE

Lot Area 20,000 FT²

_____ Basement with Plumbing _____ Basement without Plumbing X No Basement


Existing Drive
Well
Septic Tank
Trench
Trench
Trench